

JOHN AND MARY FELDERMAN FARM, STABLE
Northeast Corner of County Road 56
and County Road T
Clarkville Vicinity
Yuma County
Colorado

HABS NO. CO-129-1

HABS
COLO
63-CLK.V,
II-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Building Survey
National Park Service
Department of the Interior
Denver, Colorado 80225-0287

HISTORIC AMERICAN BUILDING SURVEY

JOHN AND MARY FELDERMAN FARM
STABLE

HABS NO. CO-129-I

HABS
COLO
63-CLK.V,
II-

Location: Southwest 1/4 of the Southwest 1/4 of Section 22, Township 5 North, Range 46 West, Sixth Prime Meridian. Yuma County, Colorado. North of the intersection of County Road 56 and County Road S, vicinity of Clarkville, Colorado.

Present Owner: Farmers Home Administration, U.S. Department of Agriculture

Present Occupant: Vacant

Present Use: None

John and Mary Felderman Farm,
Stable

HABS No. CO-129-I

(Page 1) (Page 2)

Stable

Exterior

The one and one-half story stable is constructed of 2x6 and 2x4 wood framing covered with vertical tongue and groove siding milled to resemble shiplap siding. The siding has been covered with corrugated metal sheets. The stable was built about 1915 and has had only minor alterations to the interior as the farm changed functions over the years.¹ The foundation of the stable is a perimeter sill of cast-in-place concrete. Visible above the foundation is a sill plate which is partly stabilized by an interior poured concrete slab. The simple moderately-pitched gabled roof stable is roofed with wood shingles and has boxed cornices. Today there are no extant windows in the building. There are large door openings at the two ends with overhead tracked sliding doors.

Interior

The stable has concrete slab flooring. There are six storage rooms, three on both the east and west sides that appear to have been used as horse stalls at one time but now are used for miscellaneous materials storage. The stalls face the central, north-south axis of the building which is a large open area. The interior walls are unfinished except the partial walls used to enclose the stalls. Those enclosures are made of tongue and groove siding milled to resemble shiplap siding and framed with 2x4 lumber.

Existing Condition

The building appears to be in sound condition, however, the metal sheathing may be masking rot or other problems.

Endnote

1.Appraisal Card, Parcel 63-0999-223-00-070, Yuma County Assessor's Office, Wray, CO.